

FIG. 8

***NOTE— PREVIOUS STEP NOT SHOWN FOR CLARITY.

STEP # 7 — AFTER TOP COATING THE FIRST TWO PLIES OF FLASHING; COAT THE AREAS REQUIRED TO ADHERE THE NEXT SHEET.

STEP #8 — CUT A NEW PIECE OF SHEET TO THE DIMENSIONS SHOWN IN FIG. 8.

STEP #9 — CUT ALONG THE GREEN LINES AND FOLD ALONG THE BLUE LINES.

STEP #10 — APPLY THE SHEET AS SHOWN IN FIG. 10. FOLD THE EARS AROUND THE ENDS OF THE FLANGE. TOP COAT WITH ADHESIVE. DO THIS 2X.




FIG. 10